




P15=P19=P22=P26=
=P30=P33=P35=P38=
=P40=P47




P16=P44




P17




P18=P37=P41=P51




P20



P21



P23=P24=P25=P27=P28=
=P29=P42



RELATÓRIO DO AÇO					
		20P-95		P17	
		P20		P21	
		30P-95		P45	
		P48		P49	
		P52			
ACO	N	EXAM (mm)	QUANT	C LINT (mm)	C TO
CA60	1	5,0	364	75	
	2	5,0	284	73	
	3	5,0	144	95	
	4	5,0	220	29	
	5	5,0	334	107	
	6	5,0	240	29	
	7	5,0	29	29	
	8	5,0	63	30	
	9	5,0	21	115	
	10	5,0	20	127	
CA60	11	5,0	20	37	
	12	10,0	142	321	
	13	10,0	12	285	
	14	12,5	6	285	
	15	12,5	66	330	
	16	12,5	12	83	
	17	18,0	2	207	
	18	18,0	6	341	
	19	18,0	6	341	
	20	18,0	6	341	